

Ford Romania Internship Program

Project Work Plan



Project Name:	Clean oil from rear up corner BS	Supervisor Name:	Costel Dobrica
Department Name:	Body Mainenance	Supervisor CDSID:	cdobrica
Domain of Project:	Automation / Electronics	Supervisor Position#:	ME Manager Stamping & Body
Project Description			

Actuals status: Body Side panels have oil on rear up corner. From this reason ISRA Station from 6X300 generate measured error position.

Project objective : Achieve oil cleaning system from rear up corner Body Side in Framing line.

Measurable Objectives

- Improve MTBF - Framing line
- Increase TAV

Expected Major Contributions

- Increase quality roof setting on body.

Expected Benefits to Intern

- Understand how work an automation system.

Intern Qualifications (schooling, work experience, major)

- Computer/ Electronics/ Automation studies